


## Corner rounding tooling MX700



Reference	Radius in mm	Required fittings	
MRE28	Radius from 3 to 16mm	TAP 28	CAB 46
MRE40	Radius from 16,5 to 26mm	TAP 40	CAB 60
MRE50	Radius from 26,5 to 32mm	TAP 50	CAB 78

*For different sizes, please ask the manufacturers.*


## Fiting nuts for punches MX700



Type	Fiting nuts for punches
TAP28	Nut for punches N28 <i>Standard</i>
TAP40	Nut for punches N40
TAP50	Nut for punches N50
TAP60	Nut for punches N60
TAP75	Nut for punches N75
TAP100	Nut for punches N100
ATAP	Fiting part for TAP100



## Fiting for dies MX700



Type	Fiting for dies
N46	Fiting for dies N46 <i>Standard</i>
N60	Fiting for dies N60
N78	Fiting for dies N78
N85	Fiting for dies N85
N100	Fiting for dies N100
N125	Fiting for dies N125

